

CLASSIFIED MESSAGE

ROUTING

2152Z 7 SEPT 59

SECRET

25X1

FROM

ACTION: OPS (1,2)

INFO: S/C (3)

TO

TOR: 2152Z 7 SEPT 59

ROUTINE

25X1

IN 06828

25X1

PRITY

INFO

CITE

8984

25X1

25X1

25X1

TO

1. BOTH 6037 AND 6038 80% FAILURE DUE TO IMPROPER SETTING OF PROGRAMMER.

2. WITH TAKE-OFF BEFORE SUN-RISE, MARK SHOULD BE TO RIGHT OF

AFTER SUN-RISE, MARK SHOULD BE TO LEFT.

3. CHECK MANUAL CLOSELY BEFORE ANY SET-UP.

END OF MESSAGE

SECRET

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No.

25 YEAR RE-REVIEW